



DPM 5554 Series
Coating, Metallic, Int.
Decorative

The Sherwin-Williams Company
601 Canal Road
Cleveland, Ohio 44113

October 27, 1978

Douglas Aircraft Company
3855 Lakewood Boulevard
Long Beach, Calif 90846
Attn: M.J. Veneroso, Dept. C1-725 (52-11)
Materials Handling & Packaging Engineering

Dear Sir:

We received your request for Material Safety Data Sheets for the following products:

Metallic Clear Lacquer, #T40 C P11 - DPM 5528 and DPM 5554
Reducer, #R7 K P106 - DPM 5502 " " "
Insulation Coating, F60 R 1 - DPM 458-1
Coating and Acid Component, 90G022 - DPM 1309

However, we find that these products have been discontinued by us and have not been manufactured for some years now. Therefore, we are unable to furnish the information you have requested.

If we can be of assistance with other products which are actively manufactured, do not hesitate to contact us.

Sincerely,

THE SHERWIN-WILLIAMS COMPANY

Richard J. Konchar

Richard J. Konchar
Technical Regulatory Affairs
Cleveland Technical Center

RJK/blc

DPM 5554 Series
Coating, Metallic, Int. Decorative